

SK 125

Corte de Contacto

45-85A

100-125A

Buza Exterior

487632
487631

Tobera Portabuzas

486028
486029

Buza Interior

45A · 408614
65A · 408615
85A · 408616
105A · 408612
125A · 408617

Electrodo

425023

Difusor

482135
482136

Cabezal

422675
(junta 433608)

Chapa Fina Corte Limpio

45A

482030

486028

408613

482135

Gubiado 100-125A

487640

486029

105A · 408631
125A · 408634

482136

SK 165

Corte de Contacto

45-85A

100-160A

487633
487634

486021
486022

45A · 408640
65A · 408641
85A · 408642
105A · 408643
125A · 408644
160A · 408645

482137 425024

422678
(junta 433609)

Gubiado 100-160A

487641

486022

105-125A · 408632
160A · 408633



PLASMATECH
CEA PLASMA CUTTING DIVISION

EQUIPOS PLASMA INVERTER

SHARK

Corte Manual	25 Compressor, 45, 45 SV	1~
	75, 105, 125, 155	3~
Corte Automático	75M, 105M, 125M,	3~
	125MR, 155M, 155MR	



SL 100

Patín
Distanciador
9-8422



Tobera Portabuzas

9-8218

Buza Interior

Corte
40A · 9-8208
60A · 9-8210
80A · 9-8211
100A · 9-8212
120A · 9-8253

Cartucho

9-8213

Electrodo

9-8215

Cuello 75°

9-8219
(junta peq. 8-3486
junta negra. 8-3487)


Buza Exterior

Contacto
9-8236

Máquina
9-8245

Chapa fina
9-8243

Gubiado
9-8241



9-8237

Gubiado
<40A · 9-8225(A)
50-120A · 9-8226(B)
60-120A · 9-8227(C)
60-120A · 9-8228(D)
60-120A · 9-8254(E)



**THERMAL
DYNAMICS**

*Antorcha automatización / mecanizada, consultar.